-- ABSTRACT

AZ

A method using a computer, and a recording medium, for creating an easy-to-use interface for displaying messages on a screen of the computer through the use of a controller having a pressure sensing unit. An operation pressure of a user on the controller is detected by the pressure sensing unit and a pressure sensing output value that corresponds to the operation pressure is generated. The number of message display frames that corresponds to the pressure sensing output value is determined, and that number of message display frames are displayed on the screen or monitor all at once. --